

On Wednesday, June 17th, 2020 at 5:16 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The driver had been traveling EB in the EB lanes of US-20, exited at CR-X49, and turned right onto the WB exit ramp. The WWD continued down the ramp onto the mainline and continued EB in the WB lanes of US-20.

