

On Wednesday, June 17th, 2020 at 3:58 pm a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The driver had been traveling EB in the EB lanes of US-20, exited at CR-X49, and turned right onto the WB exit ramp. The WWD self-corrected just before the first set of wrong way signs.

