

On Tuesday, June 23rd, 2020 at 2:30 pm a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The driver had been traveling EB in the EB lanes of US-20, exited at CR-X49, and turned right onto the WB exit ramp. The WWD self-corrected halfway between the Do Not Enter signs and the 1st set of wrong way signs, then turned around and went NB on CR-X49.

