

On Friday, July 10th, 2020 at 3:02 pm a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB on US-20, took the exit at CR-X49, and turned left. After crossing US-20, the WWD turned right onto the WB exit ramp. The WWD self-corrected at the second set of do not enter signs, then continued north.

