

On Tuesday, July 21st, 2020 at 10:35 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected at the first set of wrong way signs, turning around and going north on CR-X49.

