

On Tuesday, July 21st, 2020 at 5:27 pm a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling WB along the south frontage road of US-20. The driver turned right on CR-X49, crossed US-20, and turned right onto the WB exit ramp. The WWD self-corrected at the first set of wrong way signs, turning around and going north on CR-X49.

