

On Sunday, July 26th, 2020 at 10:36 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected at the second set of do not enter signs, backing up to CR-X49 and continuing north.

