

On Wednesday, July 29th, 2020 at 8:03 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected just after the first Do Not Enter signs, returning to CR-X49 and turning north.

