

On Thursday, July 30th, 2020 at 10:05 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected at the 1st set of Wrong Way signs, returning to CR-X49 and turning north.

