

On Monday, August 17th, 2020 at 9:34 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD approached from the north and turned left onto the WB exit ramp. The driver self-corrected at the second set of Do Not Enter signs. The WWD returned to CR-X49, turned left, and then went EB in the EB lanes of US-20.

