

On Wednesday, August 19th, 2020 at 8:22 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected just past the second set of Do Not Enter signs, turning around and leaving north on CR-X49.

