

On Friday, September 4th, 2020 at 10:57 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD, a flatbed truck, had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected at the second set of Do Not Enter signs, backing up to CR-X49 and leaving northbound.

