

On Wednesday, September 30th, 2020 at 4:52 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right (in front of another vehicle) onto the WB exit ramp. The WWD self-corrected just after the second set of Do Not Enter signs, returning to CR-X49 and leaving north.

