

On Thursday, October 1st, 2020 at 8:12 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD approached the interchange NB on CR-X49 from south of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected just after the second set of Do Not Enter signs, turning around and leaving north on CR-X49.

