

On Thursday, October 8th, 2020 at 7:44 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. Traffic approaching the WWD head-on stopped, prompting the WWD to self-correct at the second set of Do Not Enter signs. The driver backed up to CR-X49 and left northbound.

