

On Tuesday, October 20th, 2020 at 11:46 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp.

The WWD self-corrected at the first set of Wrong Way signs, returning to CR-X49 and leaving northbound.

