

On Tuesday, November 17th, 2020 at 8:14 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD approached from the north and turned EB onto the WB exit ramp. The driver stopped at the second set of Do Not Enter signs, backed up to CR-X49, continued across the overpass, and turned again (correctly) to go EB in the EB lanes of US-20.

