

On Wednesday, January 6th at 6:55 AM, a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected after the stop bar turning around and returning to the entrance of the ramp and leaving north on CR-X49.

