

On Tuesday, January 12th, 2021 at 9:21 PM a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.

The WWD had been traveling SB in the SB lanes of CR-X49. The driver then turned left onto the WB exit ramp. The WWD self-corrected after the end of the ramp by a U turn, and then returned to the entrance of the ramp

