On Monday, August 3rd, 2020 at 8:38 am a WWD was detected turning EB onto the WB exit ramp at CR-X49 and US-20.
The WWD had been traveling EB in the EB lanes of US-20. After crossing the overpass, the driver turned right onto the WB exit ramp. The WWD self-corrected at the 2nd set of Do Not Enter signs, backing up to CR-X49 and leaving northbound.
Ellen Kennedy Living Center
Kramer Funeral Home
Mercy Medical Center-Dyersville
X49
Dyersville Elementary School
FarmTek
Imperial Stone
X49
20
Recker Ag Services
Digga North America
JEDA Polymers
Nutrien Ag Solutions