

**LEGEND**  
**STRUCTURES...BLUE**  
**PCC PAVING...RED**  
**HMA PAVING...BLACK**  
**GRADING...BROWN**  
**SIGNS...ORANGE**  
**LANDSCAPING...GREEN**  
**REVETMENT...PURPLE**

**BRFN-009-8(44)—39-96**  
**Bridge Deck Overlay**  
**Let 02-20-24**

**STP-056-2(010)—2C-22**  
**STP-056-2(005)—2C-33**  
**HMA Resurfacing/Milling**  
**Let 03-21-23**

**NHSX-003-7(049)—3H-33**  
**Pavement Planing/Grooving**  
**Let 02-20-24**

**BRFN-150-4(63)—39-33**  
**Bridge Deck Overlay**  
**Let 02-20-24**

**HSIPX-003-6(072)—3L-09**  
**NHSX-003-6(071)—3H-09**  
**HMA Paved Shoulders/New**  
**HMA Resurfacing/Milling**  
**Let 07-18-23**

**NHSN-218-8(143)—2R-09**  
**Salvage and Removal**  
**01-17-24**

**BRF-0036(69)—38-09**  
**Bridge and Approaches**  
**Let 05-21-24**

**NHSX-218-8(134)—3H-09**  
**Bridge New PPCB**  
**Let 02-20-24**

**NHSX-218-8(124)—3H-09**  
**Grading**  
**Let 02-20-24**

**BRFN-063-6(100)—39-07**  
**Bridge Rehabilitation**  
**Let 02-20-24**

**BRF-018-7(67)—38-19**  
**Bridge Replacement—CCS**  
**Let 10-17-23**

**NHSX-150-4(064)—3H-33**  
**HMA Resurfacing**  
**Let 10-17-23**

**STPN-076-2(067)—2J-03**  
**Microsurfacing**  
**Let 11-21-23**

**STPN-009-9(094)—2J-03**  
**Bridge Repair**  
**Let 10-24-23**

**IA 9 Lansing Bridge**  
**STP-009-9(90)—2C-03**  
**Bridge Removal**  
**STP-009-9(82)—2C-03**  
**Pavement/New**  
**STP-009-9(83)—2C-03**  
**Traffic Signs**  
**STP-009-9(84)—2C-03**  
**Bridge/New—Other**  
**All Lettings—08-01-23**

**STPN-051-1(019)—2J-03**  
**STPN-051-1(021)—2J-03**  
**NHSN-018-9(119)—2R-03**  
**NHSN-018-9(124)—2R-03**  
**PCC Sidewalk/Trail**  
**HMA Resurfacing/Milling**  
**PCC Sidewalk/Trail**  
**HMA Resurfacing/Milling**  
**Let 12-19-23**

**NHSN-018-9(118)—2R-22**  
**Revetment**  
**Let 11-21-23 13**

**STPN-128-1(11)—2J-22**  
**Pipe Culverts**  
**Let 11-21-23**

**BRFN-013-3(48)—39-22**  
**Bridge Deck Overlay**  
**Let 11-21-23**


**NHSX-063-7(109)—3H-09**  
**HMA Resurfacing/CIP**  
**Let 09-19-23**

**STPN-188-1(12)—2J-09**  
**Microsurfacing**  
**Let 11-21-23**


**BRFN-218-7(239)—39-07**  
**Bridge Replacement CSS**  
**Let 11-21-23**

**NHSN-000-T9306)—2R-00**  
**Traffic Signs**  
**Let 03-19-24**

# New Hampton RCE 2024



- 1. MPIN-380-2(712)73—0N-07  
HMA Joint/Crack Sealing  
San Marnan Interchange  
Let 10-18-22
- 2. MP-218-2(706)206—76-09  
HMA Crack Filling  
Let 10-18-22
- 3. MP-057-2(708)25—76-12  
HMA Crack Filling  
Let 10-18-22
- 4. MP-024-2(710)1—76-19  
HMA Crack Filling  
Let 10-18-22
- 5. MP-346-2(708)0—76-19  
HMA Crack Filling  
Let 10-18-22
- 6. MP-013-2(714)76—76-22  
HMA Crack Filling  
Let 10-18-22
- 7. MP-009-2(712)230—76-45  
HMA Crack Filling  
Let 10-18-22
- 8. MP-063-2(708)225—76-45  
HMA Crack Filling  
Let 10-18-22
- 9. MP-009-2(709)252—76-96  
HMA Joint/Crack Sealing  
Let 10-18-22



- 10. MB-076-2(504)43—77-03  
Deck Joint Repair  
Let 01-18-23
- 11. MB-076-2(502)42—77-03  
Deck Joint Repair  
Let 01-18-23
- 12. MB-076-2(503)43—77-03  
Deck Joint Repair  
Let 01-18-23
- 13. MBIN-380-2(513)67—0M-07  
Slope Protection  
Let 03-21-23
- 14. MBIN-380-2(514)72—0M-07  
Slope Protection  
SB Flyover—N Jct US 20  
Let 03-21-23
- 15. MBIN-380-2(512)62—0M-07  
Slope Protection  
Let 03-21-23
- 16. MP-000-2(753)0—76-00  
PCC Patching  
(East Side of District 2)  
Let 03-21-23
- 17. MB-346-2(501)1—77-19  
Revetment  
Let 08-15-23

# New Hampton RCE MP 2024