










Tire tracks were visible several days later



Median cable barrier damage and tracks were also visible consistent with a median cross-over

