







Ref. Loc. 187.2
FHWA # 25170

Granular Shoulder		
2_P_FullHMA_ 04-21-20		
STATION TO STATION		Ⓞ Feet
230+72.00	231+71.48	8





PLAN VIEW

DESIGNER INFO	7156 Modified
------------------	------------------

9" HMA Paved Shoulder at guardrail.

Compaction of HMA is required to face of guardrail post. Hand compaction will be allowed under guardrail. Removal and reinstallation of guardrail will be allowed with no additional payment.

Refer to Tabulation

HORIZONTAL AND VERTICAL PROJECT CONTROL COORDINATE LISTING
HORIZ. DATUM: NAD83(2011) for EPOCH 2010.00 (laRTN 2019 Adjustment)
la. Regional Coordinate System Zone 4 (U.S. Survey Foot)
VERT. DATUM: NAVD88
Geoid Model: 2018u3


Point Name	Northing	Easting	Elevation	Code/Description
CPE	8679379.90	14963636.90	1026.24	CP SET FENO MON 36FT EAST OF CL OF FIELD ENTRANCE 55FT NORTH OF CL OF HWY3 494FT WEST OF RESIDENCE DRIVEWAY
48	8676858.33	14969797.59	1015.35	CP FND FRANKLIN CO GPS MON AS DESCRIBED IN GOOD CONDITION
41	8674116.65	14954014.13	1113.39	CP FND FRANKLIN CO GPS MON AS DESCRIBED IN GOOD CONDITION
CPW	8679335.63	1		

108_23A
8/15/22

TRAFFIC CONTROL PLAN

IA 3 will be closed during construction. Through traffic will be maintained by an offsite detour. Refer to Sheet J.2 for detour route.

ML - IA 3



ML - IA 3

