

JOURNAL

Comment	Timestamp	User
State Radio called back and advised that they did not receive any additional calls and they were unable to locate any wrong way drivers.	06/01/2018 09:28:59 PM	Nick Glenn
At 21:12 the TMC received a call from Cedar Rapids DPS reporting a "Wrong Way Driver" on US 30 from Kirkwood Blvd approximately MM 253 going east bound in the westbound lanes. The TMC activated DMS #'s 422, 417, 1831, 76 and 75 with the designated warning. At this time no wrong way drivers have been found on camera.	06/01/2018 09:22:43 PM	

DMS MESSAGE

Location	Message 1	Message 2	Start	End
US 30 WB @ IA 13-OH	WARNING WRONG WAY DRIVER REPORTED	WARNING WRONG WAY DRIVER REPORTED	09:16 PM	09:30 PM
US 30 EB @ MM 257.9-OH	WARNING WRONG WAY DRIVER REPORTED	WARNING WRONG WAY DRIVER REPORTED	09:16 PM	09:30 PM
US 30 WB - Kirkwood-OH	WARNING WRONG WAY DRIVER REPORTED	WARNING WRONG WAY DRIVER REPORTED	09:17 PM	09:30 PM
SS1831 - US 30 WB @ MM 254.6	WRONGWAY DRIVER REPORTED	WRONGWAY DRIVER REPORTED	09:17 PM	09:30 PM
US 30 EB - Edgewood-OH	WARNING WRONG WAY DRIVER REPORTED	WARNING WRONG WAY DRIVER REPORTED	09:19 PM	09:30 PM

CHANGE HISTORY

Field	Value	Timestamp	User
Milepost (Begin)	254	06/01/2018 09:15:13 PM	TMC
Direction	West	06/01/2018 09:15:13 PM	TMC
Highway	US-30	06/01/2018 09:15:13 PM	TMC
County	Linn	06/01/2018 09:15:13 PM	TMC
City	Cedar Rapids	06/01/2018 09:15:13 PM	TMC
Garage		06/01/2018 09:15:13 PM	TMC
Description	Initial report of an event on US-30 WB at MM 254 in Cedar Rapids.	06/01/2018 09:15:13 PM	TMC
Date/Time (Cleared)	06/01/2018 10:14:00 PM	06/01/2018 09:15:13 PM	TMC
Date/Time (Reported)	06/01/2018 09:14:00 PM	06/01/2018 09:15:13 PM	TMC
Date/Time (Incident)	06/01/2018 09:14:00 PM	06/01/2018 09:15:13 PM	TMC
Roadway	Yes	06/01/2018 09:15:13 PM	TMC
Estimated Duration	60	06/01/2018 09:15:13 PM	TMC
Reported By	State Patrol	06/01/2018 09:15:13 PM	TMC
Reporter Group		06/01/2018 09:15:13 PM	TMC
Priority	Routine	06/01/2018 09:15:13 PM	TMC
Incident Status	New	06/01/2018 09:15:13 PM	TMC